

# PRODUCT RECALL

## Amp Fuse Wire

Barcode number: 5013669955739

The defect may result in significant overheating of the fuse wire and associated fuse carrier and there is a potential **RISK of FIRE**.

If you have one of these items purchased from Homebase between 1st July 2011 and 31st January 2012 please **STOP USING IT IMMEDIATELY**.

Please return the product to your nearest Homebase Store for a full refund.

This recall only applies to **5 AMP FUSE WIRE** purchased between 1st July 2011 and 31st January 2012. 15 Amp and 30 Amp fuse wire supplied on the same card is not affected by this recall and operates as intended.

No other Homebase products are affected by this notice.